


BELT LOADER HANDRAIL GAP

ASA REF: -	01/20	DATE OF ISSUE: -	06/03/2020	EFFECTIVE DATE: -	06/03/2020
------------	-------	------------------	------------	-------------------	------------

Please see the below message from CAA’s Ground Handling Operations Safety Team regarding the gap presented on belt loaders:







Information sharing bulletin
OSH-XCHANGE - 1

This information has been provided by the ground handling community, regulators or Health and Safety membership organisation. The information is shared without judgement, bias or blame but to assist in the development of a learning culture within aviation ground handling environment. Please ensure this information is managed responsibly.


Hazard

A gap exists through which a person could fall.

Recommendations/ Learning outcomes

A risk assessment shall consider the fall protection methods sufficient in ensuring a person’s safety when working at height.




Issue date: January 2020
Revision number: 0

END.

Originator: -	Compliance Manager – Operations and Safety	Confirmed By: -	Head of Fire and Airfield Operations
---------------	--	-----------------	--------------------------------------