

AIRSIDE OPERATIONAL INSTRUCTION 06 & 23

SI REF -	01/2020	DATE OF ISSUE -	16 th January 2020	EFFECTIVE DATE -	16 th January 2020
AERODROME MANUAL/ AOI REF(s) -	Airside Operational Instruction 06 and Airside Operational Instruction 23				

Please see below changes to current published airside operational instructions.

Airside Operational Instruction 06 – new document issued

AOI 06 Ground Movement Handling of Airbus A380 & Antonov AN225 Aircraft (Part 1)
Above Code E Movements, Boeing B777X, B747-8, Antonov AN124 (Part 2)

is now effective. To view this document please click on the following link
<https://www.eastmidlandsairport.com/about-us/operational-documents/airside-operational-instructions/>

All departments and airside operators are asked to read this document and refresh their competency in preparation for the winter season.

Airside Operational Instruction 23

3.7 The runway contamination form is no longer in use. This is replaced by: **The runway surface should be passed to ATC via RT only.**

End

Originator -	Head of Fire and Airfield Operations	Confirmed By -	Compliance Manager Operations and Safety
---------------------	--------------------------------------	-----------------------	--